



No. 3 cottages

Fig. 17 Nos. 9 and 11
Carr Lane

Fig. 18 The well-preserved
outhouses to Nos. 9 and 11,
showing the privy to No. 9
(centre) with its emptying
hatch and ashpit alongside,
and the pigsty with its arched
doorway and a feeding hatch
beside the gate. The main
range contains a double-
stalled cowhouse and a
wash-room behind the pigsty



Fig. 19 Ermine Street,
east side. The pair in
Fig. 16 (now Nos. 10
and 12) with an earlier
cottage and a pair of No.
1 cottages beyond

(photos by K. Miller)